



IT WAS THIS SCREW HOLDING ON THE PLATE THAT WAS LOOSE, IT THEREFORE WASN'T TOTALLY SEALING THE PUMP DELIVERY CHAMBER UPTO THE FILTER HOUSING